



IGS ASIA PACIFIC
WATER SOLUTIONS

THE SOLUTIONS!

An IGS Water Conditioner



Specifications:

Thread: 2" BSPT Male
Length: 210mm
Housing: 316SS
Flow Range: 200 - 450l/min

- ✓ Protection for pumps, chlorinator cells, filters, pipes and pool surfaces
- ✓ Softer water to swim in
- ✓ Turbulence generated through the Pool 350 gives a thorough mix of chemicals and water improving efficacy
- ✓ Scum lines are more easily wiped away
- ✓ Backwash is more through
- ✓ Minerals don't deposit on the pools painted surfaces
- ✓ Better efficiency of the pump, filtration and chlorination systems over its lifespan
- ✓ Simple self installation

+61 (03) 7035 6313
info@igswater.com
www.igswater.com

IGS Asia Pacific,
Ground floor
470 St Kilda Rd
Melbourne, VIC 3000, AUS





IGS ASIA PACIFIC
WATER SOLUTIONS

A SIMPLIFIED LOOK **AT OUR ADVANCED** TECHNOLOGY



STANDARD WATER SYSTEM

Scale-causing minerals have a high electrical charge, repel each other and 'stick' to pipes and equipment causing costly hard water problems.



WITH IGS WATER CONDITIONER

The IGS Water alloy produces a turbulent mineral-attracting galvanic action reducing the electrical charge of minerals.

Non-sticking nano sized colloids are formed and flow through the system is suspension significantly reducing hard water problems.



+61 (03) 7035 6313



info@igswater.com



www.igswater.com



IGS Asia Pacific,
Ground floor
470 St Kilda Rd
Melbourne, VIC 3000, AUS





IGS ASIA PACIFIC
WATER SOLUTIONS

APPLICATIONS



Showers



Washing Machines & Dishwashers



Swimming Pools



Residential, Caravan & RV



Cooling Towers



Irrigation



Drill Rigs



Commercial



+61 (03) 7035 6313



info@igswater.com



www.igswater.com



IGS Asia Pacific,
Ground floor
470 St Kilda Rd
Melbourne, VIC 3000, AUS





IGS ASIA PACIFIC
WATER SOLUTIONS

ENHANCING
THE WORLD'S MOST
PRECIOUS
RESOURCE IN YOUR
SWIMMING POOL



- ✓ Eco-Friendly
- ✓ Chemical & Salt Free
- ✓ No Moving Parts
- ✓ Non-Sacrificial
- ✓ No Power Source Required
- ✓ Maintenance Free
- ✓ Lifetime Warranty
- ✓ Simple Self Installation

+61 (03) 7035 6313
info@igswater.com
www.igswater.com

IGS Asia Pacific,
Ground floor
470 St Kilda Rd
Melbourne, VIC 3000, AUS











IGS ASIA PACIFIC
WATER SOLUTIONS

LEFT UNTREATED
MINERALS
IN WATER WILL CAUSE
PROBLEMS
IN YOUR SWIMMING POOL



-  Salts and scale deposit on chlorinator cells reducing the capacity of the cell to maintain the required level of chlorine production
-  Excess salt and scale build up causing the cell plates to over heat leading to premature failure
-  Hard to remove scum lines on pool surfaces
-  Scale builds up on the painted pool surfaces giving them a milky look
-  Pool filters do not back wash thoroughly
-  Unexpected breakdowns of pumps and chlorinators result in costly repairs or replacement

 +61 (03) 7035 6313
 info@igswater.com
 www.igswater.com

 IGS Asia Pacific,
Ground floor
470 St Kilda Rd
Melbourne, VIC 3000, AUS














IGS ASIA PACIFIC
WATER SOLUTIONS

ARE YOU AT RISK?

Signs to look out for:

-  White spots where water has dried such as Shower screens, taps & faucets, cars, boats
-  Poor lather / low foam production from soaps and detergents
-  Dry hair and skin irritations
-  Decreased performance and increased running costs of appliances and equipment
-  Decreased performance and increased maintenance costs of evaporative air conditioners, hot water systems and appliances
-  Increased chemical usage in swimming pools and cooling towers
-  White 'chalky' appearance on surfaces
-  Premature failure of pumps, heating elements and related equipment
-  Calcification inside pipes, faucets, hot water systems, heating elements and chlorinator cells

 +61 (03) 7035 6313
 info@igswater.com
 www.igswater.com

 IGS Asia Pacific,
Ground floor
470 St Kilda Rd
Melbourne, VIC 3000, AUS

